21	East elevation	Deflection to columns and cracking which continues around to South elevation manifesting in stepped cracking. Again incorrect gable detail i.e. lack of coping and dpc detail in this particular case cement fillet has been used instead of correct lead flashing.	Rebuild entire section as detailed on dwg using re – claimed bricks and correct strength mortar. Include correct gable detailing.	