14	North elevation	Gable detail showing evidence of movement. In addition incorrect detailing of gable has resulted in water damage to mortar and brickwork. Note lack of mortar to joints surrounding corbel	Dismantle and rebuild using re – claimed bricks and correct strength mortar. Rebuilt detail to include correct coping and dpc detailing.	