Tree Safety Survey 7th September 2021 inspected by Sara Bright

Recreation Ground, Rectory Road, Tydd St Mary

Sara Bright
ARBORICULTURAL CONSULTANT

Tree no	Size band	Species	Age class	Condition/ notes	Work required	Priority
1	S4	Tilia species Lime	mature	2 trees/ stems together, in moderate condition, epicormic growth, ivy on stem, 3 long branches over road and phone lines, minor deadwood	remove epicormic growth to 3-4m, sever ivy, reduce length of the 3 branches over road by 4-5m - at appropriate points - to ensure 6m of highway clearance	3 months
2	S4	Acer pseudoplatanus Sycamore	mature	tree appears to be in moderate condition; ivy on stem, one large stem has been removed in past leaving decaying wound, minor deadwood, OHB's to phone line through crown, recent surfacing work to drive	remove 2 lowest branches at the main stem to clear phone line	3 months
3	S4	Acer pseudoplatanus Sycamore	mature	tree in poor condition; ivy clad, has been twin but one stem has failed leaving a decaying 3m wound to half stem	fell	3 months
4	S4	Acer pseudoplatanus Sycamore	mature	group of trees appear to be in moderate condition; ivy on stems, recent poor 'pruning', minor deadwood	sever ivy	6 months
5	S4	Tilia species Lime	mature	twin stemmed at 2m, appears to be in moderate condition; ivy clad stem, epicormic growth, recent poor 'pruning' and root plate disturbance, minor deadwood,	remove epicormic growth to 3-4m, sever ivy	3 months
6	S3	Ulmus species Elm	mature	dead tree, risk to neighbour	fell	asap
7	S4	Quercus robur Oak	mature	specimen tree in moderate condition, some veteran feature, low target deadwood - conservation value, brambles and vegetation around the tree deter access	no action	
8	S4	Populus species Hybrid poplar	mature	one of a boundary group 8 of trees, in moderate condition, some deadwood typical for Poplar, some OHB's to neighbour, do not appear to have been 'topped' in the past; none of this group have been, growing co-dependently, they present a low risk to neighbours and playing field, the bramble and scrub thicket around the margin deters access under the trees	no action	
9	S4	Populus species Hybrid poplar	mature	tree in moderate condition	no action	
10	S4	Populus species Hybrid poplar	mature	tree in moderate condition	no action	
11	S4	Populus species Hybrid poplar	mature	tree in moderate condition, poor form, numbered	no action	
12	S4	Populus species Hybrid poplar	mature	tree in moderate condition, large twin-stemmed	no action	
13	S4	Populus species Hybrid poplar	mature	tree in moderate condition	no action	
14	S4	Populus species Hybrid poplar	mature	tree in moderate condition	no action	
15	S4	Populus species Hybrid poplar	mature	tree in moderate condition, poor form, numbered	no action	
16	S3	mixed	mature	group of trees along the margin and around the Poplars, including Leylandii, Hazel, Sycamore, in moderate condition	no action	
17	S4	Populus species Hybrid poplar	mature	tree in moderate condition, smaller than the others in group, poor form, sub-stem	no action	

18	S4	Populus species Hybrid poplar	mature	tree in moderate condition	no action	
19	S4	Tilia species Lime	mature	tree in moderate condition, minor deadwood, OHB's to neighbour not actionable	no action	
20	S2	Ilex aquifolium Holly	mature	multi-stemmed tree in rather poor condition; fence growing into stem, ivy in crown, OHB's to neighbour	sever ivy	3 months
21	S2	Corylus avellana Hazel	mature	multi-stemmed tree in poor condition; suppressed, OHB's to neighbour and on fence	coppice at 0.5m	3 months
22	S2	mixed	mature	group of trees along boundary/ margin, in moderate condition, including Prunus, self-set Sycamore, Ash, Hazel, growing with bramble etc, this vegetation offers conservation value and protects neighbouring properties	no action for h&s	
23	S4	Populus species Hybrid poplar	mature	tree in moderate condition, sub-stem, ivy on stem	sever ivy	3 months
24	S2	mixed	mature	group of trees in the field corner, including Ash and Elm, in moderate condition, some high OHB's to neighbour - not actionable	no action	
25	S4	Populus species Hybrid poplar	mature	group of trees - 68 from corner to footbridge - in moderate condition, significant landscape feature and gives shelter to the playing field, ivy clad stems, some lower branches to neighbours, some low target deadwood, have been 'topped' in the past; would have been better to thin out the trees	sever ivy on stems, crown lift to approx 4m, remove branches to neighbours garage at main stems (informed that these trees may be pollarded this year)	3 months
26	S2	mixed	mature	group of trees and scrub growing in front of and around the Poplars, in moderate condition	no action	
27	S2	Acer pseudoplatanus Sycamore	semi mature	group of stems encroaching the footpath and footbridge	remove stems to clear	3 months
28	S4	Populus species Hybrid poplar	mature	group of 17 trees, from footbridge to boundary, in moderate condition, landscape feature and gives shelter to the playing field, ivy clad stems, OHB's to dyke and neighbours	sever ivy on stems, crown lift to approx 4m (informed that these trees may be pollarded this year)	3 months
29	S3	Acer pseudoplatanus Sycamore	mature	group of trees in the field corner, in moderate condition	no action	
30	S1	mixed	mature	margin of scrub, including rose, along the Poplars and field, has conservation value and prevents access to the dyke and under the trees	no action	
31	S4	Populus species Hybrid poplar	mature	northern boundary group of trees, in moderate condition, do not appear to have been 'topped' in the past, some deadwood typical for Poplar, OHB's and some old failures to dyke, some access bridges across the dyke to neighbours	sever ivy, remove failed stems to dyke	3 months
32	S4	Fraxinus excelsior Ash	mature	tree appears to be in moderate condition; ivy clad stem, been crown reduced in past, minor deadwood; possible early Ash dieback disease	sever ivy	3 months
33	S3	mixed	mature	group of trees, including Poplar suckers, Ash, Prunus, in moderate condition	no action for h&s	
34	S3	Ulmus species Elm	mature	ivy clad dead tree, in neighbouring property, may fail to playing field	contact owner (Anglian Water?) to make safe	3 months
35	S3	mixed	mature	trees and scrub growing in the compound and encroaching the playing field	cut back to fence line, if deemed an issue to the playing field	3 months
36	S4	Fraxinus excelsior Ash	mature	twin stemmed tree, appears to be in moderate condition; possible included union, minor deadwood, OHB's to school - not actionable	no action	
37	S4	Fraxinus excelsior Ash	mature	tree in moderate condition, ivy on stem, minor deadwood, high OHB's to school, growing with self-set Ash and Elder	sever ivy	3 months

38	S4	Fraxinus excelsior Ash	mature	tree in moderate condition, ivy on stem, minor deadwood, substems growing to school, on fence	sever ivy, crown lift to clear fence	3 months
39	S2	Fraxinus excelsior Ash	semi mature	self-set tree next to fence and utility cabinet, growing with scrub and ivy	fell and treat stump, suggest remove scrub and ivy from fence and cabinet	3 months
40	S2	mixed	mature	trees growing in the school grounds, with encroaching vegetation to the changing block	cut all back to fence line to clear the building	3 months
41	S3	Carpinus betulus Hornbeam	mature	school tree, has low branch to play area	prune to give 2.5-3m clearance if required	3 months
42	S2	mixed	semi mature	group of trees along the boundary, including Walnut, self-set Ash and Elder, in moderate condition	no action for h&s	
43	S2	mixed	mature	old hedgeline and self-set trees, with conifers - being partially cut	no action for h&s	
44						