

Appendix. Photos of site.



1 Open fronted storage building / tractor store 2 View to building from north end of site



3 Asymmetrical ridge and permeable surface. 4 Side / rear view



5 Building assimilated into landscape. 6 Building at end of existing outbuildings
Existing permeable surface refurbished