








David Aldridge Architecture Limited
 Leadenhall House, Holbeach St. Marks
 'As existing' photographs
 Sheet No. 1



East Elevation.



North Elevation.




NORTH



Planning & Development

17 MAR 2010

Ref: 0219-10




David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 2






West Elevation.



North outbuildings.





West Elevation.



North outbuildings.

SHDC
Planning & Development
17 MAR 2010
Ref: 0219-10



David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 3



West
Court yard.




West elevation.




North
elevation.

South
elevation. ↗



SHDC
Planning & Development
17 MAR 2010
0219-10
Ref: ~~0210~~

David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 4.....




Dormer
details.



Pediment
valley.




South parapet
gutters etc.




SHDC
Planning & Development

17 MAR 2010

Ref: 0219-10



South parapet
gutter/bay roofs.




Inverted dpc
2008

David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 5



1760s build.

1820s build.



E. elevation "tuck pointing"



South west corner.



Typical tuck pointing.




South west corner parapet.

SHDC
Planning & Development
17 MAR 2010
Ref: 0219-10


South east parapet




'dummy' stack on east gable CH15.



Stair window. North W. elevation.





coat hooks
Hall



Main staircase



Kitchen
GF



Typical architrave/
skirting details
Room GF 1



MS inst air & down
to lower ground floor.




Staircase
cementitious slurry
applied 2008.

SHDC
Planning & Development
17 MAR 2010
Ref: 0219-10

Typical moulding
details FF


David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 9




basement looking south.




damage to south plate/rafters.



East Attic-East Slope Room A1



first floor-East Room A1



Attic Room Frame Details




South plate + bay structure.

SHDC
Planning & Development
17 MAR 2010
Ref: 0219-10

David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 7




Fireplace-Drawing
Room GF



Plaster cornice
Room GF

SADC
Planning & Development
17 MAR 2010

Ref: 0219-10




Fireplace-Dining
Room GF




Fireplace
Room



Boy Window
Room




Fireplace
Room




Fireplace
Room


David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 8.




cupboard front
Room



Kitchen Details.



Kitchen Details.



Kitchen Details/
Fireplace. GF




TYPICAL
Mouldings



Ground Floor Room
GF1.




STAIRS
Landing FF-



Bathroom
Roof/Ceiling details.

David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 10.


SHDC
Planning & Development
17 MAR 2010
Ref: 0219-10




Barn
East elevation




Barn
North side elevation



Barn
North W. corner



Typical Gate/
Rolling Details.



Barn
North wall.



Barn
South side.

David Aldridge Architecture Limited
Leadenhall House, Holbeach St. Marks
'As existing' photographs
Sheet No. 11