




Name: IMGP1734

Date: 20/05/2004 16:43:36

Description: Left hand elevation, vertical cracking/differential settlement



Name: IMGP1738

Date: 17/05/2004 15:20:24

Description: Cracking/distortion to ground floor ceilings



Name: IMGP1739

Date: 17/05/2004 15:20:36

Description: Cracking/distortion over reception room door



Name: IMGP1740

Date: 17/05/2004 15:22:24

Description: Perished brickwork under bay window sill