



Image from Google images

This is a google image prior to the collision, this is effectively 2 damaged sliding sash windows making up the one corner unit shown in this image.



Image from Google images