



Plate 17 Manhole of Cistern on Victoria Street Site, looking east



Plate 18 Manhole of Cistern on Victoria Street Site, looking down and east



Plate 19 Manhole of Cistern on Victoria Street Site, looking down and east




Plate 20 Plate 19 lightened: Manhole of Cistern on Victoria Street Site, looking down and east



Plate 21 Cistern on Victoria Street Site, looking west from the manhole



Plate 22 South wall & two drains in Cistern on Victoria Street Site, looking south-west from manhole



Plate 23 South wall & east drain in Cistern on Victoria Street Site, looking south from manhole




Plate 24 South wall & east drain in Cistern on Victoria Street Site, looking south from manhole



Plate 25 East blocking brick wall and south wall in Cistern on Victoria Street Site, looking south-east from manhole



Plate 26 East blocking wall and south wall in Cistern on Victoria Street Site, looking south-east from manhole



Plate 27 East blocking wall in Cistern on Victoria Street Site, looking east from manhole



Plate 28 East blocking wall in Cistern on Victoria Street Site, looking east from manhole



Plate 29 North wall and east blocking wall in Cistern on Victoria Street Site, looking north-east from manhole



Plate 30 North wall and east blocking wall in Cistern on Victoria Street Site, looking north-east from manhole



Plate 31 North wall in Cistern on Victoria Street Site, looking north from manhole



Plate 32 North wall in Cistern on Victoria Street Site, looking north-west from manhole



Plate 33 Rubble within the Cistern on Victoria Street Site, looking down and west from manhole



Plate 34 Rubble within the Cistern on Victoria Street Site, looking down and west from manhole

Air raid shelter



Plate 35: The air raid shelter prior to reopening, looking southwest © Stuart Banham (flickr)



Plate 36: East elevation of the air raid shelter prior to reopening, looking west © Stuart Banham (flickr)



Plate 37: East elevation of the air raid shelter, looking southwest, showing northwest wall of former bank (left) and east wall of no. 19 Station Street (right). This photograph was taken in August 2023 after the southern entrance had been reopened IMG_2300



Plate 38: East elevation of the air raid shelter after reopening, looking west. IMG_2299




Plate 39: South entrance to air raid shelter, showing temporary door, looking west. IMG_2301



Plate 40: Bricked-in north entrance to air raid shelter, looking west IMG_2304



Plate 41: Aperture cut into brickwork of east elevation, infilled with post-war red brickwork, looking west IMG_2311




Plate 42: Opening in brickwork of east elevation close to the southern entrance, looking west IMG_2306



Plate 43: Metal bracket inserted into mortar in east elevation IMG_2305



Plate 44: North elevation of the shelter, looking south IMG_2312



Plate 45: North elevation of the shelter, looking southeast, showing wooden pegs embedded in mortar
IMG_2313



Plate 46: Narrow passage between no. 19 Station Street (left) and west elevation of air raid shelter, looking north IMG_2375



Plate 47: South elevation of the shelter, looking northeast IMG_2374



Plate 48: Concrete roof slab of the shelter, looking northeast from no. 19 Station Street flat IMG_2377



Plate 49: Outer south entrance to shelter showing interior of entrance lobby, looking west IMG_2318



Plate 50: Rear face of concrete lintel over outer south entrance, showing wooden bracket and possible imprint of former timber doorframe attachment points in the brickwork below IMG_1606



Plate 51: Close-up view of attachment point for possible doorframe in wall of outer south entrance IMG_2323



Plate 52: View of interior of south entrance lobby. The inner entrance to the shelter compartments is on the right IMG_2319



Plate 53: Close-up view of inner (south) entrance to shelter, showing incomplete simple timber frame and attachment point for probable gas curtain IMG_1607



Plate 54: View of the interior of the shelter, showing central partition wall and compartments on either side, looking north towards the inner (north) entrance IMG_1498)



Plate 55: Another view of the interior, showing compartments on each side of central wall and north cubicle (left) inner (north) entrance (right) at the far end, looking north IMG_1501



Plate 56: Interior view of inner (south) entrance (left), partially demolished central partition wall (nearest to camera) and south cubicle IMG_1510



Plate 57: Detail view showing LBC 'PHORPRES' Fletton bricks used in the construction of the central partition wall IMG_1592



Plate 58: Inner (south) entrance (left) and entrance to south cubicle (right), looking southwest
IMG_1581



Plate 59: Entrance to north cubicle (left) and inner (north) entrance, looking northeast IMG_1526



Plate 60: Timber frame attached to outer face of inner (north) entrance, looking southwest IMG_1539



Plate 61: Remains of the gas curtain at the inner north entrance to the shelter IMG_1533



Plate 62: Imprints of timber shuttering in the concrete roof slab IMG_1528



Plate 63: Exposed longitudinal metal reinforcing bars in the concrete roof slab IMG_1586



Plate 64: North end of the eastern compartment of the shelter, showing the mains electricity cable (bottom right). The high-level fuse board and a junction box can be seen above the lintel of the inner (north) entrance IMG_1548



Plate 65: Junction box and board at northern end of east compartment, showing in-situ ceiling light fitting IMG_1562



Plate 66: Ceiling light fitting in the centre of the shelter, illuminating both east and west shelter compartments IMG_1570



Plate 67: Detail view of central ceiling light fitting, showing method of attachment to roof slab
IMG_1571



Plate 68: Detail view of central light fitting, showing method of attachment for bulb IMG_1576



Plate 69: Ceiling light fitting at the south end of the shelter. This would have illuminated the area inside the south entrance to the building IMG_1585



Plate 70: Brick supports for bench seating on the floor of west shelter compartment, north end
IMG_1520



Plate 71: Timber anchor for probable bench seating in west [?] shelter compartment IMG_1578



Plate 72: Timber anchor for probable bench seating in east shelter compartment; the block has been inserted in the inner face of the east elevation of the shelter IMG_1595



Plate 73: Timber battens attached to central brick pier in west shelter compartment IMG_1577



Plate 74: Infilled post-war window opening in east wall of the shelter, looking south IMG_1558



PCA CAMBRIDGE

THE GRANARY, RECTORY FARM
BREWERY ROAD, PAMPISFORD
CAMBRIDGESHIRE CB22 3EN

t: 01223 845 522

e: cambridge@pre-construct.com

PCA DURHAM

THE ROPE WORKS, BROADWOOD VIEW
CHESTER-LE-STREET
DURHAM DH3 3AF

t: 0191 377 1111

e: durham@pre-construct.com

PCA LONDON

UNIT 54, BROCKLEY CROSS BUSINESS CENTRE
96 ENDWELL ROAD, BROCKLEY
LONDON SE4 2PD

t: 020 7732 3925

e: london@pre-construct.com

PCA NEWARK

OFFICE 8, ROEWOOD COURTYARD
WINKBURN, NEWARK
NOTTINGHAMSHIRE NG22 8PG

t: 01636 370410

e: newark@pre-construct.com

PCA NORWICH

QUARRY WORKS, DEREHAM ROAD
HONINGHAM
NORWICH NR9 5AP

T: 01223 845522

e: cambridge@pre-construct.com

PCA WARWICK

2 PLESTOWES BARN
HAREWAY LANE, BARFORD
WARWICKSHIRE CV35 8DD

t: 01926 485490

e: warwick@pre-construct.com

PCA WINCHESTER

5 RED DEER COURT, ELM ROAD
WINCHESTER
HAMPSHIRE SO22 5LX

t: 01962 849 549

e: winchester@pre-construct.com

