



Photo 1 – Front elevation



Photo 2 – Left Elevation



Photo 3 – Rear elevation



Photo 5 – Left and rear elevation

---



Photo 5 – Building F with failed left elevation, roof and covered in fire debris and contents.



Photo 6 – Workshop 1 and partition (door to) kitchen.



Photo 7- Workshop 1 and partition (door to) kitchen and access to loft void.



Photo 8 – Truss roof above kitchen extension appears to be in a reasonable condition but further inspection require upon removal of covering.



Photo 9 – Oak Kitchen within building A.



Photo 10 – Bathroom with marble splashback and very large bath.



Photo 11 – Kitchen two within Building E



Photo 12 – Kitchen two within Building E