32	South elevation	Evidence of water damage to facia/soffit detailing and pointing due to lack of guttering	Correct as part of re – building works.	