16	North elevation	Gable detail showing evidence of cracking again possibly due to incorrect strength mortar. In addition total lack of flashing detail.	Rake out joints and re - point using correct strength mortar	