10	North elevation	Gable detail showing evidence of movement. Also incorrect detailing i.e. poor/non existent dpc and coping details resulting in water damage to wall beneath *and soffit/facia details.*	Dismantle and rebuild using re – claimed bricks and correct strength mortar	