



1. Southern End of Open Fronted Building




2. East Facing Open Front.




3. South Facing Side of Main Building.




4. As Above.




5. East Facing Gable To Main Building




6. As Above.




7. North Facing Side To Main Building




8. As Above



9. West facing Elevation




10. As Above.



11. West Facing Gable To Main Building



12. Corbelled Brick Foundation To South Elevation Wall.




13. Internal View of The Main Building With Timber Tie Beam in Foreground.



14. Crack of The External Wall Local To The Timber Tie Beam Shown Above.




15. Spreader Plates To Tie Beam Shown in Photo's 13 & 14.




16. View of "Modern" infill Brickwork, Nominally Plumb, Adjoining The Outward Leaning Original Portion of Wall.




17. First Floor Within The "Cottage" Showing Temporary Support Prop Where Internal Wall Has Been Removed.




18. Timber Partition Wall Between Main & Open Fronted Buildings.



19. Localised Damage To Brickwork & Roof At South East Corner of Lean-To Portion of Main Building.



20. Internal Wall To Lean-To Portion of Main Building



21. Gable Wall To Lean-To Portion of Main Building.