
13 new bedrooms 3 and a lounge in re-built coachhouse. Building Inspector confirms that it will need to be dry-lined if solid construction and otherwise consistent with Bldg Regs MRW 06 · OCTR

Case Officer Conclusions / Report

Is open area on ground floor compatible with historic building – loss of large area of back wall –



Sash forms for shutter.

16 Nov 07 10 over 10

Ownership issue not fully resolved.

Private flats – still included.