
FARM BUILDINGS. BLACK HOLE DROVE.




1. GENERAL VIEW FROM THE EAST SHOWING THE THREE SECTIONS OF THE PROPERTY



2. VIEW FROM BLACK HOLE DROVE. LOOKING FROM THE SOUTH EAST.




3. SOUTH FACING GABLE AND "BOUNDARY" WALL




4. SOUTH GABLE SHOWING OUTWARD LEAN OF THE BRICKWORK AT THE PEAK.


NB. INTENTION IS TO TAKE DOWN AND RE-BUILD




5. VIEW ON NORTH WEST CORNER OF "HIGH" SECTION. NB THIS CORNER AND GABLE PEAK ALSO LEAN OUTWARD.




6. VIEW ON NORTH EAST CORNER SHOWING NORTH ELEVATION AND LARGE OPENING WITH LINTEL SAT UPON CORNER OF STABLE AREA.
(see photos 11 & 12)



7. + 8. TYPICAL TIMBER ROOF FRAMING FOR AGRICULTURAL STORE IS A MIX OF PURLINS AND COLLAR FRAMES WITH EAVES LEVEL TIES/STRAPS ADDED IN




ALL WILL NEED TO BE REMOVED AND RE-FRAMED TO SUIT DOMESTIC HABITATION



9. "HIGH LEVEL" ROOF FRAMING ALSO A MIX OF FRAMES AND TIES. WILL NEED TO BE REPLACED



10. EXISTING EXTERNAL WALL FOOTING IS A SMALL CORBEL, 4 COURSES BELOW GL. EXTENDING 2 COURSES TO SOIL




11. LOCAL MOVEMENT OF NORTH ELEVATION RETURN WALL



12. CRACKING BACK TO BACK WITH PHOTO 11. VIEWED FROM INSIDE "STABLE" AREA

14999 Appendix . 06



13. SLIGHT MOVEMENT OF REAR EXTERNAL CORNER (N.W.) OF HIGH LEVEL AREA



14. TWO OF THREE SHALLOW ARCHES WHICH NEED TO BE RESTORED



15. "THIRD" ARCH ON WEST ELEVATION (ref photo 14.) SHOWING LOSS OF INTEGRITY