
DD/049/001 and DD/050/001 and withdrawn in respect to this change




SOUTH HOLLAND DISTRICT LOCAL PLAN : PROPOSED CHANGES

REFERENCE No: PC/(36)/001 **INSET No: 36 - SUTTON ST. EDMUND** **DATE : JUNE 1996**

REASONS FOR CHANGE: *In response to objections received.*

1:5000 SCALE

001 and DD/050/001 and Wellg
to this exh



Cross Road

× tree removed

HORNBEAM

HORNBEAM

HORNBEAM

1m³ soakaway

1m³ soakaway

1m³ soakaway

existing Pyracantha hedge?

turning / parking

ex trees to remain

?fence/ wall

A B C

A B C

A B C

Ash

ex dyke piped and filled to local drainage boards spec

Multi-stemmed Ash.

BROADLAWNS

turning

re

1m³ soakaway

ex conifers

Existing landscaped belt. Containing Willow, Cherry, Ash, Persian Ironwood, Cornus sp. etc. (An attractive mix of trees/shrubs).

ex band of trees

turning

1 2 3 4 5

PROPOSED PARKING AREA

6 7 8 9 10

Proposed laurel hedge

ex shrubbed area

A NORWAY MAPLE

B LIME

C NORWAY MAPLE

D NORWAY MAPLE

E NORWAY MAPLE

YEW

Sorbus sp.

ex trees to remain

ex sub station

ex bus shelter

ex silver birch

PROPOSED ACCESS

PROPOSED ACCESS

proposed shrubbed area

CAVITY IN MAIN TRUNK.

BROADGATE

Possible tree works/condition.

A. Norway Maple - little dead wood to be removed.

B. Lime - Formulative thinning to move rubbing branches.

C. Norway Maple - little dead wood to be removed. Cavity in lower branch. Branch structure could be thinned out.

D. Norway Maple - Cavity in main trunk - obvious condition.

E. One duplicate branch could be removed.

Site Plan 1·250