Heritage impact assessment.

Existing cement mortar has deteriorated.

Repointing using a traditional lime mortar mix and restoration would have a positive effect on integrity of the grade 2 listed building.