
H02-0081-24 Barn Lodge, Hereward Way, Crowland, PE6 0BL

Schedule of external materials to clear Condition number 7
Revision A - Roof tile amended

| Element | Material | Website |
|---|---|---|
| Walls | Granchester Blend | https://www.traditionalbrickandstone.co.uk/bricks/grantchester-blend |
| Roof tiles | Marley Lincoln Clay Pantile | https://www.marley.co.uk/roof-tiles/clay-roof-tiles/lincoln-single-pantile |
| Pathway | Marshalls Indain Sandstone | https://www.marshalls.co.uk/gardens-and-driveways/garden-paving/indian-sandstone-paving |
| Driveway | Marshall Driveset Tegula Autumn | https://www.marshalls.co.uk/gardens-and-driveways/product/drivesett-tegula-original-block-paving |

Brick Image



Tile Image



Pathway image



Driveway image

