1.0 SCHEDULE OF CONDITION

Item	Location	Comment	Remedial Action	Photograph
1	Access track – west elevation	Significant tree adjacent to external wall, likely to be affecting foundations.	Requires removal and assessment of resulting damage to foundations	