24		Stepped cracking with evidence of partial collapse over opening	Rebuild entire section as detailed on dwg using re – claimed bricks and correct strength mortar.	