13	North elevation	Damaged mortar/pointing probably due to exposed nature of North elevation.	Rake out and re – point with correct strength mortar.	