12	North elevation	Extensive ivy growth. Note external render detail, which may be covering damaged/compromised wall detail.	Remove and re - point	