47	Store area South elevation	Ivy growing up brickwork	Remove and make good pointing using correct strength mortar	