44	South elevation	Damaged lintel, insufficient bearing.	Replace with reclaimed item.	
45	Store area	Tree adjacent to structure	Remove and dig trial hole to asses damage to adjacent foundations.	