


1 Front and left hand flank elevations to cottage. Note proximity of large willow tree.

2 Rear elevation. Note the vertical crack between the two sections of the building.






3 Close-up of damp penetration in the front, left-hand bedroom.

4 Main roof space.





5 Garage to cottage.


6 Internal view of garage to cottage.





7 Flat roof to office building.

8 Front elevation of workshop 3.





9 Workshop 3.


10 Front elevation to office.





11 Close-up of damaged brickwork to front corner of office.

12 End wall to workshop 3.






13 Workshop 2.


14 Front elevation to workshop 1.






15 End flank wall to workshop 1.

16 Rear elevation to workshop 1.





17 Interior of office.


18 Interior of workshop 1.





19 Interior of workshop 2.

20 Interior of workshop 3.





21 Further view of interior of workshop 3.