





91/2121 (21E0278)
HOLBEACH ST JOHNS

Path of LV conductor affected by tree.

Entrance to Vicarage Close

Location of tree requiring work.
Large Oak to rear of church yard.



OS REF

