
BRICK AROUND CRACK SHOULD BE REMOVED AND REPLACED WITH NEW BONDED INTO EXTRA BRICK , STEEL ELBOWS SHOULD BE BOLTED TO EXTRA BRICK AND 1.0M VERTICAL CENTRES AS BELOW FIRST FLOOR
13 11 2003