

Photo 6 showing floor beam with missing post-requires steel UB to support office floor
© S P Kidd