

29/4/01

North pond.
Building materials dumped in pond. Note line of original bank (↙).



North pond. Building materials dumped in pond.



Middle pond. 29/4/01


Removal of all top vegetation, contrary to ESL recommendations. The small area of green in the middle distance is the bank between the two ponds.



29/6/01

Middle pond.

Scraping of bank (some recommended in 'Ek Report) + complete clearance of all bankside/top vegetation — see also other photograph.



Middle pond, south end. 29/4/01
Removal of at least one osier
transplanted from top of
embankment in 1997/8

SHDC



North pond. 29/4/01
Bank scraped for 2/3rd
length



25/4/01 North pond
All top vegetation
removed.