



New brickwork to be neatly keyed into existing brick bond

Extent of damage to existing stone quoins to be surveyed post removal of facade. Care required to minimise any damage to the existing stonework during demolition

Timber glazed and panelled door

ISSUED

B	27 Apr 2009	RB	RB	Balcony line weights changed
A	17 Apr 2009	RB	RB	Door to upper levels changed. Balcony wider

3102
Planning & Development
27 APR 2009
Ref: 1197108

REVISION	DATE	DRAWN	CHECKED	DESCRIPTION	SCALE	DATE
CLIENT	Joy Centre Properties Ltd & Mr M Berwald	1:10	26 Aug 2008			
PROJECT	14 Market Place, Spalding	DRAWN	CHECKED			
JM	JM					
DRAWING TITLE	Shop Front Detail	JOB NUMBER	DRAWING NO.	REVISION		
Elevation		231432	101	B		