


LOCATION PLAN 1:2500

M. BAXTER

BRIDGE ROAD
SUTTON BRIDGE
LINC'S.

SOUTH HOLLAND D.C.
BUILDING CONTROL
-6 AUG 1998
REF H25/98

Developers are advised to establish there is no made ground or wide variations in the type of subsoil within the loaded area and no weaker type of soil exists below the soil on which the foundations rest within such depth as may impair the stability of the structure.

The deposited plans have been examined against the criteria set out in the Building Regulations. It is neither practical or reasonable to show all relevant matters on working drawings, the fact that minor matters are not mentioned does not alleviate the builder from the responsibility of non-compliance in the carrying out of site operations.