

NTERIOR VIEW OF TIMBER LINTOL
SHOWING DIAGONAL CRACKING TYPICAL
N SIMILAR LOCATIONS
DIAGONAL
CRACKING
31.5.1999