

SHDC
Planning & Development
30 JUN 2009
Ref: 0479/09

DETERMINED
PLAN

rebuild .025 Cd Cu spur
with 50acsr

replace links
with fuses

K.14396
Clay Lake primary
Cowbit feeder
Delgate spur
rebuild