SI-550352

Monitoring Details:

Level Monitoring

Provider Name: CET

Instruction Date: 09/11/2022

Reading Date:

Date of Issue: 20/03/2024

Monitoring Interval: Every 8 weeks

Number of Visits: 10

Visits Completed: 9

Visits Outstanding: 1

Client Details:

Client: Sedgwick

Job Reference: 9670775

Engineer / Handler: David McCormack

Monitored Address:

Occupier: Mr. Nigel Cross

Address: 23 West Street, Crowland, Peterborough, PE6 0EE


Telephone: 07525214794

Email: ni.cross@mac.com

Front Elevation



Site Plan


H15M
D 10M
H 8M
D 7M
6
7
REAR
5
DINING ROOM
8
A O D
9
KITCHEN
10
4
DAMAGE TAT JUNCTION OF
2 STOREY HOUSE AND 1
STOREY REAR ADDITION
3
2
FRONT
1 TBM

Level Readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/11/22	20/01/23	27/03/23	09/06/23	26/07/23	04/10/23	07/12/23	29/01/24
TBM 1	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000
2	10.0516	10.0519	10.0535	10.0522	10.0517	10.0521	10.0519	10.0517
3	10.0999	10.1001	10.1017	10.1001	10.0997	10.0997	10.1000	10.0993
4	11.0337	11.0352	11.0358	11.0352	11.0342	11.0332	11.0345	11.0333
5	11.0210	11.0222	11.0230	11.0224	11.0203	11.0182	11.0200	11.0187
6	10.2672	10.2685	10.2690	10.2684	10.2664	10.2649	10.2655	10.2637
7	10.1969	10.1977	10.1977	10.1977	10.1961	10.1963	10.1956	10.1944
8	10.2004	10.2018	10.2007	10.2004	10.2007	10.2009	10.2015	10.2005
Taken by	N.A	N.M	P.M	T.P	N.M	K.W	E.C	L.D
Serial number	1211065	15	521856	1212418	15	7626	1212103	190

Level Movement (Displayed in Millimeters)

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/11/22	20/01/23	27/03/23	09/06/23	26/07/23	04/10/23	07/12/23	29/01/24
TBM 1	0	0	0	0	0	0	0	0
2	0	+0.3	+1.9	+0.6	+0.1	+0.5	+0.3	+0.1
3	0	+0.2	+1.8	+0.2	-0.2	-0.2	+0.1	-0.6
4	0	+1.5	+2.1	+1.5	+0.5	-0.5	+0.8	-0.4
5	0	+1.2	+2	+1.4	-0.7	-2.8	-1	-2.3
6	0	+1.3	+1.8	+1.2	-0.8	-2.3	-1.7	-3.5
7	0	+0.8	+0.8	+0.8	-0.8	-0.6	-1.3	-2.5
8	0	+1.4	+0.3	0	+0.3	+0.5	+1.1	+0.1

Level Readings - Continuation of levels

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/11/22	20/01/23	27/03/23	09/06/23	26/07/23	04/10/23	07/12/23	29/01/24
9	10.2029	10.2048	10.2041	10.2037	10.2035	10.2037	10.2050	10.2034
10	10.1840	10.1830	10.1827	10.1822	10.1817	10.1815	10.1821	10.1804
Taken by	N.A	N.M	P.M	T.P	N.M	K.W	E.C	L.D
Serial number	1211065	15	521856	1212418	15	7626	1212103	190

Level Movement (Displayed in Millimeters) - Continuation of readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/11/22	20/01/23	27/03/23	09/06/23	26/07/23	04/10/23	07/12/23	29/01/24
9	0	+1.9	+1.2	+0.8	+0.6	+0.8	+2.1	+0.5
10	0	-1	-1.3	-1.8	-2.3	-2.5	-1.9	-3.6

Level Readings

	Visit 9	Visit 10	Visit 11	Visit 12	Visit 13	Visit 14	Visit 15	Visit 16
	20/03/24							
TBM 1	10.0000							
2	10.0517							
3	10.0997							
4	11.0332							
5	11.0188							
6	10.2645							
7	10.1952							
8	10.1998							
Taken by	L.D							
Serial number	190							

Level Movement (Displayed in Millimeters) - Continuation of readings

	Visit 9	Visit 10	Visit 11	Visit 12	Visit 13	Visit 14	Visit 15	Visit 16
	20/03/24							
TBM 1	0							
2	+0.1							
3	-0.2							
4	-0.5							
5	-2.2							
6	-2.7							
7	-1.7							
8	-0.6							

Level Readings - Continuation of levels

	Visit 9	Visit 10	Visit 11	Visit 12	Visit 13	Visit 14	Visit 15	Visit 16
	20/03/24							
9	10.2035							
10	10.1810							
Taken by	L.D							
Serial number	190							

Level Movement (Displayed in Millimeters) - Continuation of readings

	Visit 9	Visit 10	Visit 11	Visit 12	Visit 13	Visit 14	Visit 15	Visit 16
	20/03/24							
9	+0.6							
10	-3							

SI-550352

Level Readings Chart (Points TBM 1 - 10)

