


1. FRONTAGE ONTO FOXES LOWE RD.



2. VIEW FROM EAST TO REAR OF PLOT.



3. FRONT ELEVATION SHOWING WALL CRACKING BETWEEN GROUND & 1ST FLOOR WINDOWS – MATCHING CRACKS ON INSIDE.




4. SIDE ELEVATION – WEST FACING. UPPER WINDOW + "NEW" DOOR OPENINGS IN POSITIONS WHICH WEAKEN WALLS.



5. REAR ELEVATION.
NOTE "DIP" AT EACH END OF ROOF LINE WHERE CHIMNEY WEIGHTS APPLY.



6 REAR OF SINGLE STOREY STORAGE AREA



7. LID TO SURFACE WATER CISTERN, JUST BEYOND BATHROOM, WHICH EXTENDS BELOW WALL.



8. BROKEN + LEAKING SURFACE WATER DRAIN — WATER "UNDERCUTS" GROUND BELOW COTTAGE GABLE WALL.