

## Supporting images for the removal of the Magnolia tree

The Magnolia because of size and being too close to the building (300mm from the wall face) is reducing sunlight and airflow to this part of the building. This has inhibited the natural drying process for managing moisture within a solid-walled property and is damaging the mortar and brick work, as show in images below.


Complete access is now need to the front elevation of the property to properly repair the damage caused by this tree.











It also blocks light to the front room and overhangs the neighbours property extensively.