

New vertical disc cut channel to form a vertical dpc weather stop on the junction with the existing wall / new door opening.
Bike Store
4275
2419
Stainless steel render stop bead applied to corner.
Zone for appliances requiring Gas and extract ventilation.
X 5.200m
2141
Kitchen.
(Kitchen design / layout By Others)
Heat Detector
3271
Wall to be removed as dotted subject to advice of structural engineer.
Inner Area of raft foundation specification over existing concrete
3519