
Magellan Way Local Wildlife Site - The Issues

PARSONS + WHITTLEY

Fly tipping is contaminating the pond and is becoming an eyesore, and this encourages more tipping, all at the expense of the habitat and the amenity of the neighbourhood.



A fine group of protected Ash trees along Magellan Way will almost inevitably succumb to the Ash Dieback disease which is spreading across the country



The pond is becoming clogged with reeds, and could soon contain no water which the site-specific insects and invertebrates rely upon for existence

sheet 2

RIBA Chartered Practice

This line measures 200mm in length when printed correctly

Project:
Proposed Dwelling
Pond, off Magellan Way
Spalding

Client:
Mr & Mrs J Retchless

drawing number: 3204.16 rev:

Title:
The Current Situation

Revision Details:

Issue Date: 23-02-17

Parsons + Whittley Ltd Architects
1 London Street, Swaffham
Norfolk, PE37 7DD
Phone: 01760 722000
email: info@parsonswhittley.co.uk
web: www.parsonswhittley.co.uk

size: A1