(Revised 9 June 2015) To concur with ecologist's comments we clarify – only the branches overhanging Magellan Way at the north eastern end of the site are to be cut back in line with the verge - Tree no. 1 Ash (T6 in ecologist's email) and Tree no. 3 Ash (just south of T1). Disturbing the dense ivy on these trees should be avoided.

To whom it may concern

Re: The Pond, Magellan Way, Spalding PE11 2FG

We write to obtain consent for maintenance work required to be carried out on trees at the above site.

Three trees within a group Tree Preservation Order tree belt along the western side of the site, between the pond and Magellan Way require attention. The trees are in the north eastern corner of the site.


Tree No. 1 Ash – Cut back branches in line with verge which overhanging Magellan Way Road, leaving tree proportionally balanced.

Tree No. 2 Willow – A few of the branches above the pollarding may need be removed along the road side edge, none of the main stems are to be cut into.

Tree No. 3 Ash – Tree just south of tree no. 1. Thin branch over hanging road should be cut back in line with verge.



Site location plan illustrating position of trees




Cut back over hanging branches

avoid disturbing any dense ivy

on the trees

Magellan Way



Cut back overhanging branches

Prue Kahn ..... P. Kahn ..... (Tree Technician)
NCH, RFS Cert in Arb. (Theory)
For and on behalf of Plandescil Ltd.

Date ..... 9th June 2015 .....

STANDARD CONDITIONS OF INVESTIGATION AND REPORTING

This report was prepared and provided for the sole and specific use of the client. Plandescil Ltd shall not be responsible for any use of the report or its contents for any other purpose. Copies of the report to other parties for information should be copied in full but Plandescil Ltd shall extend no professional liability or warranty to other parties in this connection without written consent. The copyright of this report and other plans and documents prepared by Plandescil Ltd are owned by them.

Moncrieff, Evelyn

From: John Retchless <john@johnretchless.com>
Sent: 17 June 2015 18:45
To: _planningadvice
Subject: FW: H16-0355-15 Works to Spalding TPO 016/19/1985, Pond, Magellan Way, Spalding
Attachments: 19585 Revised Tree Maintenance Works June 2015.pdf

-------- Original message --------
From: johnr <john@parsonswhittley.co.uk>
Date:17/06/2015 17:19 (GMT+00:00)
To: john@johnretchless.com
Cc:
Subject: FW: H16-0355-15 Works to Spalding TPO 016/19/1985, Pond, Magellan Way, Spalding

Dear Sir/Madam

Could you please forward this email to Diane Fairchild-Fenton as our emails sent direct are being bounced back without receipt.

John Retchless RIBA

Parsons + Whittley Ltd

Tel 01760 722000

From: johnr
Sent: 12 June 2015 15:36
To: dfairchild@sholland.gov.uk
Subject: H16-0355-15 Works to Spalding TPO 016/19/1985, Pond, Magellan Way, Spalding

Dear Diane

In the light of your comment posted on the SHDC website for the above application, I have reviewed the arboriculturalist's maintenance report and notice that the extent of the works to the trees in the north-eastern corner of the site is slightly unclear.

I have discussed this with Prue Kahn at Plandescil and an amended version of their report is attached. The amendment now includes pruning works to the slender branch of the Ash tree (slightly south of the Willow) which overhangs the road. To clarify, the proposed maintenance pruning covers the three trees in the NE corner of the site only: the two Ash trees which overhang the road, and the willow tree portion (above the pollard only) which leans toward the road in order to reduce the risk of this elderly portion from falling toward the highway.

Regards

John Retchless RIBA

for and on behalf of Parsons + Whittley Ltd

1 London Street, Swaffham, PE37 7DD

Tel 01760 722000

www.parsonswhittley.co.uk