












FLOOR ORIGINALLY SUPPORTED ON WOODEN POSTS WHICH HAVE ALL ROTTED OFF AT GROUND LEVEL RANDOM BRICK PIERS WERE ADDED TO HELP SUPPORT THE SAGGING WALLS

NO INSULATION IN WALLS OR CEILING AND ONLY 2 OPENING LIGHTS FOR VENTILATION

ROOF GREEN MINERAL FELT
WALLS HARDBOARD OVER TONGUE & GROVE






SCALE 1:50

ORIGINAL
TIMBER BUNGALOW AT
3 THE RESERVOIR
SURFLEET SPALDING
LINCS PE11 4DJ

SUPERSEDED
SUPERSEDED

DETERMINED
PLAN

-8 OCT 2008
1057/08