
Grounds

The grounds are well maintained and no other issues were noted. The maturing 'Tree of Heaven' tree located in the far left corner of the property is protected by a Tree Preservation Order and branches overhang neighbouring properties. Normal maintenance is recommended. We strongly recommend the District Council is contacted before undertaking any works to the tree.



Tree of Heaven.



Rear garden.

photo taken by surveyor in 2017. Tree is even bigger now.

[redacted]

PAULINE FRENCH

26/4/21

NO4 T1 2005