31	Open fronted storage area	Poor support/corbel detail. Damaged by poor gable wall detailing and subsequent water damage.	Partially demolish and rebuild with correct detail using re – claimed bricks and correct strength mortar	