30	Open fronted storage area	Poor support/corbel detail	Partially demolish and rebuild with correct detail using re – claimed bricks and correct strength mortar		