28	Open fronted storage area	Poor roof covering detail roof structure in good condition. Incorrect roof support detail with evidence of impact damage.	Strip off, counter batten and re cover. Replace support detail with reclaimed item to include correct jointing detail.	
29	Open fronted storage area	Poor support jointing detail, evidence of impact damage.	Replace with re – claimed item to include correct jointing detail.	