PHOTOGRAPHS.

CONTENTS:


1. The site adjacent to Alderlands Close,Peterborough Rd.Crowland.

2.Looking from the site along Peterborough Rd.towards Peterborough.

3.Looking from the site across Peterborough Rd.

4.Looking from the site along Peterborough Rd.towards Crowland.

5-8.Showing current condition of site,caused by the dumping of garden refuse & litter.



1



2



3



4



5



6



7



8

