Peter Smallwood Consulting Engineers Ltd.
Peter Smallwood, CEng, MICE Tel/Fax: 01522 529098

Job No:


Sheet No:

Job:

Date:



DETERIORATION OF FLOOR JOISTS.



CRACKS IN RENDER.