Online Comment

Application	H09-1266-16
Location	Land adjacent: 72 Church Street Holbeach Spalding PE12 7LL
Proposal	Details of landscaping, boundary treatment, ground investigation and materials (Conditions 3, 4, 5 and 6 of H09-0770-16)

Name	J Reith
Address	Environmental Health Technician Safety and Environment
Date Submitted	13-01-17
For/Against	Comments

The Combined Phase I Desk Study and Phase II Exploratory Investigation Report by GeoDyne satisfies part of the contaminated land condition. However the report identifies that further investigations are necessary on the site post demolition. Therefore the contaminated land condition cannot be fully discharged at this time.