north
west east
south

Unable to Survey area
due to being Overgrown
G2 - C1
Mixed species

Heap of Unknown Material
Unable to survey due to Nettles

Unable to Survey area due to being Overgrown
G3 - C1
Mixed species

T0707 - C1
Ash
G1 - C1
Mixed Species Group

Assumed Boundary line

H1 - B1
Privet

H2 - C1
Cypress

Assumed building line
BUILDING B
BUILDING A
Assumed building line

G4 - C1,2
Cypress

NT1 - C1
Birch

Assumed building line

G6 - B1,2
Mixed species

47

G5 - C1,2
Mixed species

T0708 - B1,2 Ash
T0709 - B1,2 Birch
T0710 - B1,2 Oak
T0711 - B1,2 Norway Maple
T0712 - B1,2 Horse Chestnut
T0713 - B1,2 Horse Chestnut

KEY
Grade A Trees
Grade B Trees
Grade C Trees
Grade U Trees
Extent of Root Protection Area
Extent of Canopy
Extent of Canopy - Groups
Trees to be Felled and Replaced
Shade Footprint

20 0 20 40 60 80 100
Metres

Rev	Date	Detail
B	31/01/23	DETAILS AMENDED
A	17/01/23	DETAILS AMENDED

i-LID DESIGN LTD
INTERIOR DESIGN | ARCHITECTURE | PROJECT MANAGEMENT
8 Sutcliffe Road, Wittering, peterborough, PE8 6AY
Tel: 07588 441751 info@i-lid.co.uk
www.i-lid.co.uk

Client: TEARS RECOVERY

Job Title:
PROPOSED TEARS RECOVERY SITE
BRIDGE ROAD
LONG SUTTON
LINCS

Scale: 1-500 @ A2 Date: 10/12/21

Drawing Title
EXISTING SITE PLAN

Drawing No.
448SD02 Revision B

ALL DRAWINGS ARE THE COPYRIGHT OF i-LID DESIGN