Online Comment

Application	H13-1278-16
Location	Fen Gate Moulton Chapel Spalding PE12 0XL
Proposal	Details of contaminated land (Condition 7 of H13-0073-16)

Name	J Reith
Address	Environmental Health Technician Safety and Environment
Date Submitted	15-02-17
For/Against	Comments

The Desk Study Report Ref. 65494R1 dated November 16 by Envirosmart satisfies the contaminated land condition. Please note that Section 2.6 of the report recommends a 'Watching brief during the entire development' in order to locate and deal with unexpected contamination.