
PHOTOGRAPHIC PLATES



INVESTORS
IN PEOPLE

Platinum
Until 2022

Coverage across the UK from offices in London, Reading, Exeter, Rutland, Nottingham, Llandudno, Chester, Manchester, Leeds and Newcastle

www.smitherspurslow.com

Registered Office: Glaston Hall, Spring Lane, Glaston, Oakham, Rutland LE15 9BZ
Smithers Purslow Limited, Registered in England Number 1402539

GLASTON HALL
SPRING LANE, GLASTON
RUTLAND LE15 9BZ
t. 01572 822000
e.glaston@smitherspurslow.com

PHOTOGRAPHIC PLATES



Plate 1. Rear left-hand barn.



Plate 2. Graffiti indicates construction 1995.

Cont'd overleaf.../



Plate 3. Rear elevation, climbing vegetation and lean-to structure.



Plate 4. Low level concrete and high level cladding to walls.

Cont'd overleaf.../



Plate 5. Internal structure and grain store partially used.



Plate 6. Concrete frame.

Cont'd overleaf.../



Plate 7. Rear right-hand barn.



Plate 8. Vegetation around rear corner.

Cont'd overleaf.../



Plate 9. Concrete frame with central wall.



Plate 10. Lower level brick and upper cladding to walls.

Cont'd overleaf.../



Plate 11. Concrete floor present.



Plate 12. Minor spalling to concrete.

Cont'd overleaf.../



Plate 13. Some vegetation internal.



Plate 14. Localised wear and tear.

Cont'd overleaf.../



Plate 15. Front barn to left-hand side.



Plate 16. Vegetation present.

Cont'd overleaf.../



Plate 17. Vegetation in close proximity to barn.



Plate 18. Brick walls and cement cladding to roof.

Cont'd overleaf.../



Plate 19. Current storage use of old equipment.



Plate 20. Timber roof structure.

Cont'd overleaf.../



Plate 21. Minor cracking in entrance.